

50271086

SURFACE INSPECTION  
COMPLIANCE REPORTDate of Inspection: April 26, 2001Case Serial No.: UTU-078278Operator: Levin StoneProject Description: Mining/Staging AreaLegal Description: Secs. 3 and 4 T. 18 S., R. 13 W.Field Office: FillmoreInspector: Sheri WysongREPORT NARRATIVE (REFERENCE STIPULATIONS BY NUMBER OR TITLE)

The quarry in Section 4 has been recontoured, but I could see no evidence that seed was applied to it. It's probably too late in the year to do so now, and should wait until next year when the rest of the disturbance has been ripped and prepared for seed. The operator has submitted a \$9000 reclamation bond for the site.

A noticeable number of pallets have been removed from the staging area in Section 3. Phil Levin told me during a phone conversation on April 16 that he plans to have all the stone out of there soon.

Signature of InspectorSignature of Authorized Officer